

Stanley Black & Decker

USA SERVICE OPERATIONS TECHNICAL SERVICES DEPARTMENT SERVICE BULLETIN

SB06175

PAGE 1 OF 1

ISSUED: June 14, 2019
Written By: K. Butler
UPDATED: November 14, 2019

SUBJECT: TESTS TO RUN BEFORE INSERTING BATTERY
UNITS: ALL FLEXVOLT
DATE CODES AFFECTED: ALL 54 VOLT

This troubleshooting guide along with a multi-meter can be used to help identify abnormal and no run tool conditions due to control module MOSFET damage. This can cause FLEXVOLT battery failure (54V mode only).

Do not connect a FLEXVOLT battery to the tool until this test has been completed if the tool is a no run.

Date: _____ Tool Catalog #: _____ Tool Serial #: _____ Tool Build Date: _____

