
PLEASE CHECK STOCK OF MODULE 643115-01 AND SEPARATE INTO GOOD AND BAD STOCK


PLEASE BE AWARE THAT
THESE MODULES MUST ONLY
BE HANDLED USING AN ANTI
STATIC MAT

## Complete module 643115-01




THIS AREA NEEDS INSPECTING

## GOOD MODULE WITH BUTTON IN PLACE




LOOK CLOSELY AS THIS IS ALSO A GOOD MODULE WITH BUTTON IN PLACE


YOU CAN SEE THE JOIN, IF YOU LOOK CLOSELY




THIS IS A BAD MODULE WITH BUTTON MISSING




THIS BUTTON IS VERY SMALL




IF BUTTON IS LOOSE IN
THE ANTI-STATIC BAG OR
THE CARTON PICK UP WITH
SMALL PLIERS OR
TWEEZERS



INSERT THE BUTTON BACK INTO THE MODULE



WITH BUTTON BACK IN PLACE DEPRESS THE BUTTON AND YOU SHOULD HEAR THE SWITCH CLICK ON AND OFF



IF THIS BUTTON IS MISSING THE TRIGGER ON THE NAILER CANNOT WORK AND THESE MODULES ARE USELESS