




## DeWalt Jigsaw – Yoke Screw Down Station.

- A) Locate the yoke onto the shaft and line up the screw holes to the clamping block, as shown.
- B) Ensure the yoke is seated correctly on shaft flats.



Yoke is screwed down with flats showing which will cause failure of shaft rotating causing blade alignment to be out or sticking shaft

**1) Screws fully down.  
0.8 Nm**



**2) Yoke seated correctly on flats.**

**3) Yoke moves freely.**

